



FACILITY COMPLIANCE INSPECTION REPORT

Division of Waste Management Solid Waste Section

UNIT TYPE:											
Lined MSWLF		LCID		YW		Transfer		Compost		SLAS	COUNTY: Lincoln PERMIT NO.: SLAS-55-01 FILE TYPE: COMPLIANCE
Closed MSWLF		HHW		White goods		Incineration		T&P		FIRM	
CDFL		Tire T&P / Collection		Tire Monofill		Industrial Landfill		DEMO		SDTF	

Date of Site Inspection: 11/14/12

Date of Last Inspection: 08/21/12

FACILITY NAME AND ADDRESS:

Dennis Hoyle Services
 7337 Reeps Grove Church Rd.
 Vale, NC 28168

GPS COORDINATES: N: 35.5330° E: -81.42381°

FACILITY CONTACT NAME AND PHONE NUMBER:

Dennis Hoyle
 Office: (704) 276-2080
 Cell: (980) 429-0438

FACILITY CONTACT ADDRESS:

P.O. Box 84
 Vale, NC 28168

AUDIT PARTICIPANTS:

Bill Wagner, Environmental Senior Specialist – Solid Waste Section
 Andrea Keller, Environmental Senior Specialist – Solid Waste Section

STATUS OF PERMIT:

Current – Issued March 31, 2011 Expires: March 2, 2016

PURPOSE OF SITE VISIT:

Comprehensive Site Inspection and annual collection of soil sample.

STATUS OF PAST NOTED VIOLATIONS:

N/A

OBSERVED VIOLATIONS

None.

You are hereby advised that, pursuant to N.C.G.S. 130A-22, an administrative penalty of up to \$15,000 per day may be assessed for each violation of the Solid Waste Statute or Regulations. For the violation(s) noted here, you may be subject to enforcement actions including penalties, injunction from operation of a solid waste management facility or a solid waste collection service and any such further relief as may be necessary to achieve compliance with the North Carolina Solid Waste Management Act and Rules.

FACILITY COMPLIANCE INSPECTION REPORT
Division of Waste Management
Solid Waste Section

Page 2 of 4




Figure 1: Dennis Hoyle Septic Site – Breezewood Lane, Vale, Lincoln Co., NC 28168
Approximate location and limits of one septage land application field.
(Lincoln Co. GIS Aerial Photo with Property Lines.)

COMMENTS

1. Mr. Wagner and Ms. Keller gained access to the facility with the permission of Dennis Hoyle. Mr. Hoyle provided a check for \$50.00 for the cost of analyzing two soil samples from the septage land application fields.
2. No one was on site during the inspection.
3. Proper signage was displayed at the entrance to the site.
4. Approved setbacks appear to be properly maintained. (i.e. distances from wells, homes, etc.)
5. There were no objectionable odors detected during the inspection.
6. The cover crop was well established and well maintained with no bare areas.



1. Looking (NE) from the lower end of field #1 towards the access gate to field #2.

2. Looking (S) across field #2.

FACILITY COMPLIANCE INSPECTION REPORT
Division of Waste Management
Solid Waste Section

Page 3 of 4

Please contact me if you have any questions or concerns regarding this inspection report.



Bill Wagner

Environmental Senior Specialist

Regional Representative

Phone: 828-296-4705

Sent on: 11/30/12		Email		Hand Delivery	X	US Mail		Certified No. _____
-------------------	--	-------	--	------------------	----------	------------	--	---------------------

ec: Tony Gallagher, Compost & Land Application Branch Head
Jason Watkins, Western District Supervisor – Solid Waste Section
Liz Patterson, Compost & Land Application Branch